

Attachment B

Summary of Distribution Circuit Field Inspection by ICC Staff			
Utility:	CILCO	Date:	7/16/01
Circuit:	181-001 (Groveland)	Inspector:	J. D. Spencer, G. E. Rockrohr, J. L. Prange
Gen. Notes: A significant portion of this circuit is underground. Trees in the overhead portions of the circuit were generally trimmed and in good shape. Many of the downguys throughout the circuit did not have guy markers.			
Map No.	Item Description	Photo(s)	Location
4 of 14	Single phase spacer cable against oak tree limb	A1, 2	3 1/2 spans west of Springfield Rd. on Broadway St.
4	Downguy damaged (strands cut)		North of Allentown Rd. in tap serving Sta. 331663
4	Broken insulator (on neutral)		Allentown Rd. at tap to Sta. 321172
7 (3 of 4)	Maple tree into primary, w/burning	A3, 4	Laura Dr. & Roberts St., Groveland
7 (3 of 4)	Flashed pothead & cutout on primary riser	A5	West & Norman Sts., Groveland
8	Tree problem		East of Safe Rd. in tap to Sta. 333228
11 (1 of 2)	Wood pin through arm (neutral)		At Sta. 331667 in radial tap going west from Springfield Rd.
14 (1 of 3)	Primary in maple tree	A6	E. Muller Rd. just west of Pinecrest Dr.